

PROBEYE[®] INFRARED VIEWER
INSTRUCTIONS FOR
DC TO DC CHARGING ADAPTER
643D4108

1. Insert black plastic connector into vehicle cigarette lighter socket.
2. Insert blue connector into PROBEYE Infrared Viewer battery charger socket.
3. With vehicle engine off, charging time is the same as the A.C. plug-in charger, I.E. 16 hours, or four hours for every hour used. With vehicle engine running, charging time is half as much.

C A U T I O N

INSTALL IN VEHICLE WITH 12VDC NEGATIVE GROUND
SYSTEM ONLY.